Division of Oil, Gas, & Mining Mining Report

01/11/95

MINE ID: S0190031

MINE NAME: CISCO SPRINGS #1

OPERATOR: JONES, MIKE CONTACT: MIKE JONES

ADDRESS: 5600 S HIGHWAY 191

MOAB UT 84532

PHONE: (801)259-8511

Surface Owner: STATE

BLM #:

Mineral Owner: STATE

Lease #:

Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1

Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2

Sec Town Range 16 20.0S 23.0E 9 20.0S 23.0E

E2 NW

Permit Status: APP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: ACT

Acreage:

Status Date: / /

Minerals Mined

DATE RECEIVED

04/05/93

TENTATIVE APPROVAL FINAL APPROVAL LAST INSPECTED DATE

1 1

DATE

04/07/93

BOND TYPE:

BOND AMOUNT:

ANNUAL REPORT YEAR: 94

YTD Total

NONCOMP NOTICES: 0

0 DATE ISSUED:

DATE RESOLVED: DATE RESOLVED:

DATE ISSUED: / /
DATE ISSUED: / /
DATE REC'D: / /
DATE REC'D: / / VIOLATIONS: 0 0 REVISIONS: 0 0

DATE APPROVED:

AMENDMENTS:

DATE APPROVED:

COMMENTS:

MECHANICAL FILTERING PROCEDURE TO PROCESS ORE. SLURRY IS PUMPED FROM CISCO WASH INTO A BUILDING ALREADY ON SITE. AFTER PROCESSING, WATER IS SETTLED IN SMALL POND THEN RETURNED TO THE WASH. OPERATOR WAS TOLD TO CONTACT DWQ CONCERNING THE SLURRY, TAILINGS POND & DISCHARGE. ALSO TOLD TO CONTACT WATER RIGHTS IN PRICE TO SEE IF PERMIT IS NEEDED TO PUMP WATER FROM CISCO WASH. 1993 REPORT STATED THAT TESTING OF MACHINERY & ORE SAMPLING IS ONLY THING BEING DONE. NO ACTIVITY REPORTED ON '94 REPORT; SHOWED SECTION 9 (NOI SHOWED 16).